# **Rockchip Linux Audio Trouble Shooting**

ID: RK-PC-YF-996

Release Version: V0.1.0

Release Date: 2023-04-25

Security Level: □Top-Secret □Secret □Internal ■Public

#### DISCLAIMER

THIS DOCUMENT IS PROVIDED "AS IS". ROCKCHIP ELECTRONICS CO., LTD. ("ROCKCHIP") DOES NOT PROVIDE ANY WARRANTY OF ANY KIND, EXPRESSED, IMPLIED OR OTHERWISE, WITH RESPECT TO THE ACCURACY, RELIABILITY, COMPLETENESS, MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE OR NON-INFRINGEMENT OF ANY REPRESENTATION, INFORMATION AND CONTENT IN THIS DOCUMENT. THIS DOCUMENT IS FOR REFERENCE ONLY. THIS DOCUMENT MAY BE UPDATED OR CHANGED WITHOUT ANY NOTICE AT ANY TIME DUE TO THE UPGRADES OF THE PRODUCT OR ANY OTHER REASONS.

#### **Trademark Statement**

"Rockchip", "瑞芯微", "瑞芯" shall be Rockchip's registered trademarks and owned by Rockchip. All the other trademarks or registered trademarks mentioned in this document shall be owned by their respective owners.

#### All rights reserved. ©2023. Rockchip Electronics Co., Ltd.

Beyond the scope of fair use, neither any entity nor individual shall extract, copy, or distribute this document in any form in whole or in part without the written approval of Rockchip.

Rockchip Electronics Co., Ltd.

No.18 Building, A District, No.89, software Boulevard Fuzhou, Fujian, PRC

Website: <u>www.rock-chips.com</u>

Customer service Tel: +86-4007-700-590

Customer service Fax: +86-591-83951833

Customer service e-Mail: fae@rock-chips.com

### Preface

#### Overview

This document mainly describes the common problems and solutions encountered in the development of audio applications on Linux platform using the rockit multimedia framework.

### **Intended Audience**

This document (this guide) is mainly intended for:

Technical support engineers

Software development engineers

### **Revision History**

Version	Author	Date	Change Description	
V1.0.0	Minxu Lin	2023-04-25	Initial version	

#### **Contents**

#### **Rockchip Linux Audio Trouble Shooting**

- 1. AI(AUDIO INPUT) Problems
  - 1.1 AI Staccato
  - 1.2 AI Frame Skip
  - 1.3 AI Set The Output Length To Desired Length
  - 1.4 AI Output Mono Audio
  - 1.5 AI Constant Frequency Interference
  - 1.6 AI VQE Enabling Method
    - 1.6.1 Library Dynamic Linking Method
    - 1.6.2 Library Static Linking Method
    - 1.6.3 Library File Unlinked Situation
    - 1.6.4 AI VQE Profile config aivqe.json
    - 1.6.5 Notes On Echo Cancellation Function
  - 1.7 AI SED Enabling Method
    - 1.7.1 Library Dynamic Linking Method
    - 1.7.2 Library Static Linking Method
    - 1.7.3 Library File Unlinked Situation
  - 1.8 AI blocking or insufficient audio input cache error reported
- 2. AO(AUDIO OUTPUT) Problems
  - 2.1 AO No Sound Output
  - 2.2 AO Staccato
  - 2.3 AO System Busy
  - 2.4 AO Stop Audio Sound Before It Is Finished Playing
  - 2.5 AO Playing Mono Audio
- 3. AIO Common Problems
  - 3.1 Sound Card Open Error

# 1. AI(AUDIO INPUT) Problems

### 1.1 AI Staccato

Generally, it is caused by untimely data retrieval. You can see if there are any overrun logs, similar to the following:

card:hw:0,0: overrun

- Need to confirm the timeliness of upper level data retrieval.
- Configure environment variables:

export rt audio period size=1024

## 1.2 AI Frame Skip

It is generally related to the parameter s32UsrFrmDepth set to RK\_MPI\_AI\_SetChnParam. If there is a situation where the u32Seq interval in the frame structure obtained by RK\_MPI\_AI\_GetFrame is greater than 1, set s32UsrFrmDepth to -1.

If AI is bound to subsequent levels such as AENC or AO, it is also necessary to use RK\_MPI\_AI\_GetFrame to retrieve the flow of AI. If frame skipping occurs, s32UsrFrmDepth needs to be set to greater than 1.

## 1.3 AI Set The Output Length To Desired Length

Set the parameter u32PtNumPerFrm of "RK MPI AI SetPubAttr" to the desired output length.

# 1.4 AI Output Mono Audio

When AI need to output mono audio, set the second parameter of RK\_MPI\_AI\_SetTrackMode to AUDIO\_TRACK\_FRONT\_LEFT (change left channel to mono) or AUDIO\_TRACK\_FRONT\_RIGHT (turn the right channel into a single channel).

# 1.5 AI Constant Frequency Interference

Usually caused by hardware problems, it is necessary to communicate with the audio driver engineer.

## 1.6 AI VQE Enabling Method

### 1.6.1 Library Dynamic Linking Method

Push libaec\_bf\_process.so, librkaudio\_common.so into the device.

### 1.6.2 Library Static Linking Method

The bin file directly links to the algorithm library file, as follows:

```
-Wl,--whole-archive libaec_bf_process.a -Wl,--no-whole-archive librkaudio_common.a
```

#### 1.6.3 Library File Unlinked Situation

Print error log:

```
failed to link to VQE Library
```

### 1.6.4 AI VQE Profile config\_aivqe.json

config\_aivqe.json needs to be pushed into the device and the path set to the corresponding parameter required by the RK\_MPI\_AI\_SetVqeAttr.

Each module within the json file can be turned on and off by setting the status parameter to enable or disable, as shown below:

```
"status" : "enable"

"status" : "disable"
```

#### 1.6.5 Notes On Echo Cancellation Function

The echo cancellation function requires at least one ref channel, so the number of input audio channels should be at least 2. The enabling methods for different chip ref channels are as follows:

• RV1106/RV1103

```
Enable ref channel method:
RK_MPI_AMIX_SetControl(s32DevId, "I2STDM Digital Loopback Mode", (char
*)"Mode2");
Disable ref channel method:
RK_MPI_AMIX_SetControl(params.s32DevId, "I2STDM Digital Loopback Mode", char
*)"Disabled");
```

#### • RV1126/RK3588

According to the hardware of the sound card, configure asound.conf.

The prerequisite is that the kernel config is configured with the following settings:

```
CONFIG_SND_ALOOP=y
```

asound.conf的参考如下:

```
pcm.!default
   type asym
   playback.pcm "plug:multi_ply"
   capture.pcm "plug:multi_cap"
pcm.multi_ply {
   type multi
   slaves.a.pcm "hw:0,0"
   slaves.b.pcm "hw:7,0,0"
   slaves.a.channels 2
   slaves.b.channels 2
   bindings.0.slave a
   bindings.0.channel 0 # Codec Left Channel
   bindings.1.slave b
   bindings.1.channel 0 # ALOOP Left Channel
pcm.multi_cap {
   type multi
    slaves.a.pcm "hw:0,0"
   slaves.b.pcm "hw:7,1,0"
   slaves.a.channels 2
   slaves.b.channels 2
   bindings.0.slave a
   bindings.O.channel 0 # Codec Left Channel
   bindings.1.slave b
   bindings.1.channel 0 # ALOOP Left Channel
```

The subsequent drivers will support software recovery, and the usage method will refer to the kernel documentation configuration.

# 1.7 AI SED Enabling Method

### 1.7.1 Library Dynamic Linking Method

Push librkaudio\_detect.so, librkaudio\_common.so into the device.

### 1.7.2 Library Static Linking Method

The bin file directly links to the algorithm library file, as follows:

```
-Wl,--whole-archive librkaudio_detect.a -Wl,--no-whole-archive librkaudio_common.a
```

## 1.7.3 Library File Unlinked Situation

Print error log:

```
failed to link to SED Library
```

## 1.8 AI blocking or insufficient audio input cache error reported

Usually, it is because RK\_MPI\_AI\_ReleaseFrame was not called in a timely manner to release the buffer.

# 2. AO(AUDIO OUTPUT) Problems

## 2.1 AO No Sound Output

• Check if the sound card exists:

```
// View mounted sound card
//RV1106/RV1103
ls /dev/snd/
//RV1126/RK3588
cat /proc/asound/cards
```

### 2.2 AO Staccato

Generally, it is caused by delayed data delivery. You can see if there are any underrun logs, similar to the following:

```
card:hw:0,0: underrun
```

- Need to confirm the timeliness of upper level data transmission.
- Configure environment variables:

export rt\_audio\_period\_size=1024

Alternatively, change the value of u32PtNumPerFrm in RK\_MPI\_AO\_SetPubAttr to 4096.

## 2.3 AO System Busy

Generally, it is caused by the unreasonable timeout setting for sending data to RK\_MPI\_AO\_SendFrame or the slow write speed caused by opening RK\_MPI\_AO\_SaveFile.

Unreasonable timeout setting can be resolved by setting the timeout to -1, which is blocking mode, or by setting it to blocking mode and counting the time difference required for RK MPI AO SendFrame to set the timeout.

## 2.4 AO Stop Audio Sound Before It Is Finished Playing

Usually, the situation of stopping before the playback is completed is caused by not calling RK\_MPI\_AO\_WaitEos after sending the last audio frame with RK\_MPI\_AO\_SendFrame.

## 2.5 AO Playing Mono Audio

When playing mono audio, set the second parameter of RK\_MPI\_AO\_SetTrackMode to AUDIO TRACK OUT STEREO (dual channel output, if mono input, make a copy).

## 3. AIO Common Problems

## 3.1 Sound Card Open Error

You can see logs similar to the following:

```
cannot set hw params: Invalid argument
TinyAlsaHardWare 12:41:56-407 {tinyalsa_pcm_get_e:051} fail to tinyalsa_open_snd,
error:cannot set hw params: Invalid argument
```

Generally caused by unreasonable sound card parameter settings, including the following situations:

• When AI and AO are started simultaneously, the sound card sampling rate (soundCard. sampleRate) is inconsistent.

Solution: when AI and AO are started simultaneously, it is necessary to ensure that the sound card sampling rate is consistent. Different AI audio output sampling rates and AO input sampling rate settings can be achieved through resampling.

 When AI outputs mono audio or AO inputs mono audio, RK\_MPI\_AI\_SetTrackMode or RK\_MPI\_AO\_SetTrackMode is not called

Solution: refer to AI Output Mono Audio and AO Playing Mono Audio .

• When setting sound card parameters such as sampling rate, number of channels, or bit width, the sound card does not support it, resulting in an error message

Solution: query the formats supported by hardware and drivers.